MATERIAL SAFETY DATA SHEET

Section 1 - Material Identity	
Product Name: PTR –Plastic Trim Restorer -#7241	Product Use: Touch Up & Plastic Repair Coating
Manufacturer(s) Supplier (s) Name & Address Telephone Number: (215) 698-0500	
ARDEX LABORATORIES, INC. 2050 BYBERRY ROAD PHILADELPHIA , PA 19116	Days: (215) 698-0500 Nights: CHEMTREC: 800/424-9300
DOT Proper Shipping Name: Flammable liquids, n.o.s, 3, UN1993, III (contains propanol, citrus terpenes)	

Section 2 - Physical & Chemical Characteristics

V.O.C.: 415 grams /liter. OTC VOC Compliant from 2011 for Air dried Touch up and Plastic Repair Coating			
	Solubility in Water by Weight: insoluble	Boiling Point: n/a	
Appearance and Odor: clear light amber color thin liquid:- HAVE A SLIPPERY FELL AND A CHARACTERISTIC alcohol-HYDROCARBON-LIKE and Citrus odor ODOR.	Specific Gravity: 0.800-1.00 (@60 DEG. F.)	Freezing Point: n/a.	
Vapor Pressure at 20EC: n/a	Percent Volatile by Volume: < 85%	Evap. Rate (Butyl Acetate=1): NEGLIGIBLE	

Section 3 - Ingredients & Specifications

Materials	%	TLV	Hazard	CAS Number
Hydrotreated Light Petroleum Distillate		100 ppm	COMBUSTIBLE	64742-47-8
2-PROPANOL		400-500 PPM	FLAMMABLE	67-63-0
CITRUS TERPENE		30 PPM	FLAMMABLE	94266-47-4
ORGANIC POLYMER**		10 mg/m3		
**Trade Secret				

Section 4 - Fire & Explosion Hazard Data

Flash Point & Method: >72 DEG F.	Tag Closed Cup	(ASTM D-56)		
Flammable Limits in Air % by volume:	Lower: N/A	Upper: N/A		
Extinguishing Media: Carbon dioxide-				
Special Fire Fighting Procedures: N/A				

Unusual Hazards: This product contains a flammable liquid. There is a possibility of producing vapor from this liquid at elevated temperature. This vapor may be ignited by heat, sparks, flame or other sources of ignition. Vapors may travel considerable distances to a source of ignition where they may ignite, flashback or explode. Vapor/air explosion hazard indoors/outdoors or in sewers. Vapors are heavier than air and may accumulate in low areas. If container is not properly cooled, it may explode in the heat of fire.

Section 5 – Health Hazard Data

Route of Entry	a) Skin:
Effects of Acute Exposure:HEALTH:1FLAMMABILITY:2PHYSICAL HAZARD:0PERSONAL PROTECTION:A	 a) Skin Contact: PROLONGED OR REPEATED CONTACT MAY CAUSE REDNESS, BURNING AND DRYING OF THE SKIN. b) Eye Contact: May cause stinging, tearing, redness, & swelling. c) Swallowing: May cause irritation of the digestive tract, signs of nervous system depression (E.G., headache, drowsiness, dizziness, loss of concentrations and fatigue.
	d) Skin Absorption: PROMPTLY WASH AFFECTED AREA WITH MILD SOAP AND WATER. REMOVE CLOTHING IF PRESENT. IF IRRITATION OR REDNESS PERSISTS GET MEDICAL ATTENTION.
Chronic Effects of Overexposure:	EXPOSURE TO HIGH CONCENTRATIONS OF THIS MATERIAL (E.G., IN ENCLOSED SPACES OR WITH DELIBERATE ABUSE) MAY BE ASSOCIATED WITH CARDIAC ARRHYTHMIAS. EPINEPHRINE AND OTHER SYMPATHOMIMETIC DRUGS MAY INITIATE CARDIAC ARRHYTHMIAS IN PERSONS EXPOSED TO THIS MATERIAL. REPORTS HAVE ASSOCIATED REPEATED & PROLONGED OCCUPATIONAL OVEREXPOSURE TO SOLVENTS WITH PERMANENT BRAIN & NERVOUS SYSTEM DAMAGE.

Other Health Hazards:	N/A		
Emergency and First Aid Procedures:	a) Skin: RINSE WITH rubbing alcohol and WATER. IF IRRITATED WASH WITH MILD SOAP AND WATER. CONTAC PHYSICIAN.		
	b) Eyes: FLUSH IMMEDIATELY WITH LARGE AMOUNTS OF WATER FOR 15 MINUTES, LIFTING UPPER AND LOWER LIDS OCCASIONALLY. GET MEDICAL ATTENTION.		
	c) Swallowing:Do NOT induce vomiting. Give two (2) glasses of water. Contact physician		
	d) Inhalation: REMOVE TO FRESH AIR. ADMINISTER OXYGEN IF BREATHING IS DIFFICULT. CONTACT PHYSICIAN.		
Carcinogen Evaluation N	/A		
Section 6 - Reactivity Data			
Stability -	Yes		
Conditions to Avoid for Stability	See below		
Incompatibility (Materials to Avoid) -	Avoid strong acids or bases, oxidizing agents & selected amines. This product forms combustible and/or explosive mixtures with air or oxygen.		
Hazardous Polymerization -	Will not occur		
Hazardous Decomposition/Byproducts	Carbon Monoxide and/or Carbon Dioxide.		
Section 7 - Spill or Leak Pr			
Release/Spill Procedures	VENTILATE AREA. ABSORB INTO NON- REACTIVE MEDIA SUCH AS DIATOMACEOUS EARTH OR VERMICULITE; SWEEP INTO NON- REACTIVE VESSEL (I.E., STEEL DRUM OR PAIL)		
Section 8 - Special Protecti	on Information		
	Eyes: USE DUST AND SPLASH-PROOF SAFETY GOGGLES WHERE THERE IS ANY POSSIBILITY OF LIQUID, MIST OR DUST CONTACTING THE EYES.		
Protective Equipment	Respirator: RECOMMENDED DUST MASK in enclosed area		
	Gloves: WEAR IMPERMEABLE GLOVES (BUTYL OR HEAVY VINYL LATEX TYPE)		
	Other: PROTECTIVE EQUIPMENT – IF POSSIBILITY EXISTS FOR SPLASHING WEAR FACEGUARDS WITH SIDE SHIELDS. USE RESPIRATOR WHEN WORKING IN A TOTALLY CLOSED SYSTEM.		
Ventilation	General Mechanical: None required		
	Other: USE IN A WELL VENTILATED AREA		
Section 9 - Special Precaut	ions		
Handling & Storage	General:		
	Other:		
Section10- Other Informat	ion		
correctness. The conditions or methods of l other reasons, we do not assume responsibil	n data considered accurate. However, the information is provided without any warranty, expressed or implied, regarding its nandling, storage, use and disposal of the product are beyond our control and may be beyond our knowledge. For this and ity for personal injury or property damage to vendees, users or third parties caused by the material. We also do not assume ty for loss, damage or expense arising out of or in any way connected with the handling, storage, use or disposal of the		
Prepared By: ARDEX LA	BORATORIES, INC. New/Revision Date: 12/12/2012		

ARDEX LABORATORIES, INC.